Yellow

Docket No. 50-302 License No. DPR-72

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-302/88-08

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by G. A. Hallstrom on March 8-11, 1988. The inspection included a review of activities authorized for your Crystal River facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

four attention is invited to the unresolved item identified in the inspection report. This matter will be pursued during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2. Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Alan R. Herdt, Chief Engineering Branch Division of Reactor Safety

Enclosure: NRC Inspection Report

cc w/encl:

P. F. McKee, Director, Nuclear Plant Operations E. C. Simpson, Director, Nuclear Site Support

bcc: (See page 2) B804150172 B80407 PDR ADOCK 05000302 Q DCD IEOI

bcc w/encl: NRC Resident Inspector DRS Technical Assistant Document Control Desk State of Florida

GAMen 1 strom: es 03/21/88

#114 #381ake |0341 /88

RVCrlenjak 4 087 6/88