

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-346/88003(DRSS)

Docket No. 50-346

License No. NPF-3

Safeguards Guards IV

Licensee: Toledo Edison Company
Edison Plaza
300 Madison Avenue
Toledo, OH 42652


Facility Name: Davis-Besse Nuclear Power Station

Inspection At: Davis-Besse Site, Oak Harbor, Ohio

Inspection Conducted: January 11-15, 1988


Date of Last Security Inspection: October 21-30, 1987

Inspector:


Bryan Drouin
Security Inspector

1/28/88
Date

Approved By:


James R. Creed, Chief
Safeguards Section

1/28/88
Date

Inspection Summary

Inspection on January 11-15, 1988 (Report No. 50-346/88003(DRSS))

Areas Inspected: Security Plan/Implementing Procedures; Management Effectiveness; Security Organization; Records and Reports; Testing and Maintenance; Physical Barriers - Protected and Vital Areas; Lighting; Compensatory Measures; Assessment Aids; Access Control - Personnel, Packages and Vehicles; Detection Aids - Protected Area; Alarm Stations; Personnel Training and Qualifications; Safeguards Contingency Plan; Protection of Safeguards Information and licensee action on previous findings.

Results: Three of four previous findings were closed. The fourth finding, which involved improvements to the surveillance system, should be completed soon. The licensee was in compliance with NRC requirements in all 18 inspected areas. The security program was well managed, was effective, and received good support from corporate and plant staff. Security infractions committed by non-security personnel require continued management attention.

(Details: UNCLASSIFIED SAFEGUARDS INFORMATION)

8802030023 880128
PDR ADOCK 05000346
G PDR

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled