



Boston Edison

Pilgrim Nuclear Power Station
Rocky Hill Road
Plymouth, Massachusetts 02360-5599

10CFR50.54(a)(3)

July 1, 1997
BECo Ltr. 2.97.070

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

License DPR-35
Docket 50-293

Annual Report of Changes to the
BOSTON EDISON QUALITY ASSURANCE PROGRAM DESCRIPTION

As required by 10CFR50.54(a)(3), Boston Edison Company (BECo) submits the annual summary of changes made to the Boston Edison Quality Assurance Program Description as listed in the Boston Edison Quality Assurance Manual (BEQAM), Volume II. This report covers the period from July 1996 through June 1997.

During this reporting period, changes to Section 18 of the BEQAM II were made. These changes were determined by BECo to be a reduction in previous commitments. In accordance with 10CFR50.54, these changes were submitted to the NRC staff on May 1, 1996. These changes were approved by the NRC on November 12, 1996, as Revision 30 to Section 18. There have been no other changes in the Quality Assurance Program Description previously approved by the NRC.

Nancy L. Desmond
Nancy L. Desmond
Group Manager
Regulatory Relations

RLC/TLS/sjs/BEQAM

cc: Mr. Alan B. Wang, Project Manager
Project Directorate I-1
Mail Stop: 14B2
U.S. Nuclear Regulatory Commission
1 White Flint North
11555 Rockville Pike
Rockville, MD 20852

U.S. Nuclear Regulatory Commission
Region I
475 Allendale Road
King of Prussia, PA 19406

Senior NRC Resident Inspector
Pilgrim Nuclear Power Station



9707090208 970701
PDR ADDCK 05000293
P PDR

1/1
2004

1/0