JAN 2 9 1988

Docket Nos. 50-348, 50-364 License Nos. NPF-2 and NPF-8

Alabama Power Company
(ATTN: Mi. R. P. McDonald
Senior Vice President
F. C. Box 2641
Birmingham, AL 35291-0400

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-348/87-36 AND 50-364/87-36

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by R. W. Newsome and J. L. Coley on December 12-16, 1987. The inspection included a review of activities authorized for your Farley facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

ALAN R. HERDT

Alan R. Herdt, Chief Engineering Branch Division of Reactor Safety

Enclosure: NRC Inspection Report

cc w/encl: (See page 2)

8802030368 880129 PDR ADOCK 05000348 G PDR

TEOI

cc w/encl:
W. O. Whitt, Executive Vice President
D. Woodard, General Manager Nuclear Plant
W. G. Hairston, III, Vice President
Nuclear Support
W. McGowan, Manager-Safety Audit
and Engineering Review
W. K. Osterholtz, Supervisor-Safety
Audit and Engineering Review

bcc w/encl:
WRC Resident Inspector
DRS Technical Assistant
UE. Reeves, Project Manager, NRR
Document Control Desk
State of Alabama

RII yew RNewsome:1b 01/j9/88 Moley Molniess 8117 #81ake 01/21/88 HDance 01/24/88