

January 25, 1988

Docket No. : 030-03537  
License No.: 53-00458-04  
Control No.: 70651

Department of the Army  
Commander, Tripler Army Medical Center  
ATTN: HSHK-RP (Rad. Prot. Office)  
Tripler AMC, Hawaii 96859

Attention: John D. Huber, Jr.  
First Lieutenant  
Acting Chief, Administrative Services

Gentlemen:

Enclosed is the NRC license amendment which you requested.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify us so that we can provide appropriate corrections and answers.

Although Item 19 of your application has been amended to reference Regulatory Guide 8.20, Rev. 1, it should be noted that 10 CFR 35.315(a)(8) requires that bioassays be performed for each individual who helped prepare or administer a therapeutic dose of iodine-131. This section of the regulations became effective on April 1, 1987.

Also, please note that 10 CFR 20.207 requires that licensed materials be secured from unauthorized removal. The radioactive waste area labeled 2H201 on Enclosure 13 of your letter dated September 16, 1987, as well as all other areas where licensed materials are used or stored, should be locked when unattended by authorized personnel.

Any future correspondence relating to your license should specifically reference your license and docket numbers to expedite your inquiry.

Sincerely,

8802030508 880125  
REQS LIC30  
53-00458-04 PDR

RV BAR  
RIEDLINGER  
1 125188

Beth A. Riedlinger  
Health Physicist (Licensing)  
Nuclear Materials Safety Section

Enclosure: Attachment A  
Amendment No. 52 to License No. 53-00458-04