Alabama Power Company 600 North 18th Street Rost Office Box 2641 Birmingham, Alabama 35291 Telephone 205 323-5341

Alan R. Barton

ATLANTA, GEORGIA

78 NOV 20 All: 28



November 17, 1978

Joseph M. Farley Nuclear Plant - Unit 2 NRC Inspection of September 12-15, 1978 File: A-35.10

Log: 78-233

Mr. James P. O'Reilly U. S. Nuclear Regulatory Commission 230 Peachtree Street NW - Suite 1217 Atlanta, Georgia 30303

Re: RII:MDH 50-364/78-14

Dear Mr. O'Reilly:

The inspection report transmitted by Mr. Murphy's letter of October 26, 1978, has been reviewed by all concerned parties and we do not consider any of the information contained therein to be proprietary.

The following represents actions taken in response to the item noted in the inspection report.

5. Electrical (Cables and Terminations I) Observations of Work and Work Activities (Details II)

Infraction 364/78-14-02, Failure to follow procedures

- A. Electrical has taken the following steps to resolve the above subject discrepancy:
  - 1. The tray AIE-45 and the cables in tray AHK-27C were reworked to comply with design criteria.
  - 2. The power cable (2VBDGO6P) was reworked to comply with design criteria.
- B. Corrective steps which will be taken to avoid further noncompliance:

NRC Inspection of September 12-15, 1978 November (7, 1978 Page 2 1. A directive concerning cable trays being used as scaffolds and for ladders was issued to all field personnel by the Construction Manager stating that violators are subject to disciplinary action if caught in cable trays. 2. The Project Manager has implemented the placement of signs stating, "Keep Off the Cable Tray," in various locations on the project. C. Full compliance has been achieved as of November 10, 1978, by our action taken in paragraph "A" above. Very truly yours, alan R. Barton by # Xe ARB: CBBh cc: Mr. M. D. Hunt