

In Reply Refer To:  
Docket: STN 50-482/87-37

Wolf Creek Nuclear Operating Corporation  
ATTN: Bart D. Withers  
President and Chief Executive Officer  
P.O. Box 411  
Burlington, Kansas 66839

Gentlemen:

This refers to the inspection conducted by Mr. D. E. Norman of this office during the period December 7-11, 1987, of activities authorized by NRC Operating License NPF-42 for the Wolf Creek Generating Station and to the discussion of our findings with members of your staff at the conclusion of the inspection.

Areas examined during the inspection included a followup and participation in a sample selection for Compliance Bulletin 87-02; and a followup of actions regarding IE Information Notice 86-53 and other identified heat shrinkable tubing problems. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspector. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

One unresolved item consisting of several parts is identified in paragraph 2.b(6) of the enclosed inspection report. You are requested to respond, in writing, to each part of the unresolved item.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

L. J. Callan, Director  
Division of Reactor Projects

Enclosure: (see next page)

RIV:RI *REN*  
DNorman:df  
1/14/88

C:PSS *RE*  
RIreland  
1/20/88

D:DRS  
JMilhoan  
/ /88

D:DRP  
LJCallan  
/ /88

Reconcur:  
RIreland  
/ /88

8802080117 880202  
PDR ADOCK 05000482  
G PDR

*LED*  
*11*

FEB 2 1988

In Reply Refer To:  
Docket: STN 50-482/87-37

Wolf Creek Nuclear Operating Corporation  
ATTN: Bart D. Withers  
President and Chief Executive Officer  
P.O. Box 411  
Burlington, Kansas 66839

Gentlemen:

This refers to the inspection conducted by Mr. D. E. Norman of this office during the period December 7-11, 1987, of activities authorized by NRC Operating License NPF-42 for the Wolf Creek Generating Station and to the discussion of our findings with members of your staff at the conclusion of the inspection.

Areas examined during the inspection included a followup and participation in a sample selection for NRC Compliance Bulletin 87-02; and a followup of actions regarding IE Information Notice 86-53 and other identified heat shrinkable tubing problems. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspector. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

One unresolved item consisting of several parts is identified in paragraph 2.b(6) of the enclosed inspection report. You are requested to respond, in writing, to each part of the unresolved item.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

The response requested by this letter and the accompanying Notice is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Sincerely,

L. J. Callan, Director  
Division of Reactor Projects

Enclosure: (see next page)

RIV:RI*	C:PSS*	D:DRS *
DNorman:df	RIreland	JMilhoan
/ /88	/ /88	/ /88

\*See previous concurrence

*DRP*  
DRP:P/A  
DChamberlain  
2/2/88

*Reconcur*  
D:DRP  
LJCallan  
2/2/88

*RIreland*  
Reconcur:  
RIreland  
2/2/88

In Reply Refer To:  
Docket: STN 50-482/87-37

Wolf Creek Nuclear Operating Corporation  
ATTN: Bart D. Withers  
President and Chief Executive Officer  
P.O. Box 411  
Burlington, Kansas 66839

Gentlemen:

This refers to the inspection conducted by Mr. D. E. Norman of this office during the period December 7-11, 1987, of activities authorized by NRC Operating License NPF-42 for the Wolf Creek Generating Station and to the discussion of our findings with members of your staff at the conclusion of the inspection.

Areas examined during the inspection included a followup and participation in a sample selection for Compliance Bulletin 87-02; and a followup of actions regarding IE Information Notice 86-53 and other identified heat shrinkable tubing problems. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspector. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

One unresolved item consisting of several parts is identified in paragraph 2.b(6) of the enclosed inspection report. You are requested to respond, in writing, to each part of the unresolved item.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

The response requested by this letter and the accompanying Notice is not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Sincerely,

L. J. Callan, Director  
Division of Reactor Projects

Enclosure: (see next page)

RIV:RI\*  
DNorman:df  
1/28/88

C:PSS  
RIreland  
1/28/88

D:DRP  
JMilligan  
1/29/88

D:DRP  
LJCallan  
1/88

Reconcur:  
RIreland  
1/88

\*See previous concurrence

Wolf Creek Nuclear Operating  
Corporation

-2-

Enclosure:  
Appendix - NRC Inspection Report  
50-482/87-37

cc w/enclosure:  
Wolf Creek Nuclear Operating Corporation  
ATTN: Otto Maynard, Manager  
of Licensing  
P.O. Box 411  
Burlington, Kansas 66839

Wolf Creek Nuclear Operating Corporation  
ATTN: Gary Boyer, Plant Manager  
P.O. Box 411  
Burlington, Kansas 66839

Kansas Corporation Commission  
ATTN: Robert D. Elliott, Chief Engineer  
Fourth Floor, Docking State Office Building  
Topeka, Kansas 66612-1571

Kansas Radiation Control Program Director

bcc to DMB (1E01)

bcc distrib. by RIV:

Myron Karman, ELD, MNBB (1)

\*RRI

\*Section Chief (DRP/A)

RPSB-DRSS

\*RIV File

\*MIS System

\*Project Engineer, DRP/A

\*Lisa Shea, RM/ALF

\*DRS

D. Powers

\*C:PSS

R. D. Martin, RA

\*DRP

J. M. Hinds, RIII

Resident Inspector, RIII

\*RSTS Operator

\*R. Hall

\*P. O'Connor, NRR Project Manager

\*TSS

\*D. Norman

\*w/766