

Northeast
Utilities System

Millstone Offices • Rope Ferry Rd., Waterford, CT

P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791

July 7, 1997
Docket No. 50-245
B16547

Re: 10CFR50.73(a)(2)(i)
Re: 10CFR50.73(a)(2)(ii)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


This letter forwards supplemental Licensee Event Report (LER) 96-012-01, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 1 on December 3, 1995. This LER is submitted pursuant to 10CFR50.73(a)(2)(i) and 10CFR50.73(a)(2)(ii).

This supplemental report provides the revised cause of the event as well as the revised completed corrective actions. In addition, the revised safety significance for this LER supplement reflects the historical concurrent existence of more than one potential failure during a design basis accident within the same system.

There are no commitments made within this letter. All other statements made within this letter are for information only.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY


P. D. Hinnenkamp
Director, Unit Operations

Attachment: LER 96-012-01

cc: Dr. W. D. Travers, Director, Special Projects
H. J. Miller, Region I Administrator
S. Dembek, NRC Project Manager, Millstone Unit No. 1
T. A. Easlick, Senior Resident Inspector, Millstone Unit No. 1

9707140345 970707
PDR ADOCK 05000245
S PDR

