



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

July 12, 1985

*TVA  
Udall Comm.*

MEMORANDUM FOR: Tom Rehm  
Assistant to the Executive Director for Operations

FROM: *[Signature]* Carlton Kammerer, Director  
Office of Congressional Affairs

SUBJECT: JULY 10 RESPONSE TO REP. UDALL'S APRIL 26  
LETTER ON HPCI FAILURES AT BROWNS FERRY

The staff of the Subcommittee on Energy and the Environment has requested we provide the following information in support of the Commission's July 10 letter:

1. Who assigned NSRS the task of investigating the pressure transmitter?
2. The response to Question 2 indicates that from 1983 to 1985, eighteen inspections involved HPCI-related problems. Please provide copies of these inspection reports and all LER's on the Browns Ferry HPCI failures.
3. Please provide a copy of reference 5.
4. Please provide the results of interviews with NSRS personnel.
5. IE Inspection Report 50-327/81-15 (page 8) indicates that on July 25, 1980, RII and TVA held a management meeting to discuss unresolved item 327/80-24-06. Please provide the December 18, 1980 TVA letter mentioned in the inspection report.

cc: Chairman Palladino  
Commissioner Roberts  
Commissioner Asselstine  
Commissioner Bernthal  
Commissioner Zech  
OGC  
OPE  
SECY

*8508070143* XA  
*-P*

*107*