

SEP 08 1993

DCD/DCB

The Cleveland Cliffs Iron Company  
ATTN: Robert G. Clark  
Radiation Protection Officer  
504 Spruce Street  
Ishpeming, MI 49849

License No. 21-03076-01  
Docket No. 030-04814/070-01721

Dear Mr. Clark:

This refers to the routine safety inspection conducted by Robert P. Hays of this office on August 3 through August 13, 1993, of activities authorized by NRC Byproduct Material License No. 21-03076-01, and to the discussion of our findings with Carlos Maki and you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities were found to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosure, and your response to this letter will be placed in the NRC Public Document Room.

The response directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Gary L. Shear, Chief  
Nuclear Materials Inspection  
Section 2

Enclosure: Notice  
of Violation

bcc w/enclosure:  
PUBLIC

RIII  
*[Signature]*  
Hays/bt  
09/07/93

RIII  
*[Signature]*  
Shear  
9/8/93  
160075

**IE07**  
PUBLIC