

APPENDIX B

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 50-267/87-29

Operating License: DPR-34

Docket: 50-267


Licensee: Public Service Company of Colorado (PSC)
2420 W. 26th Avenue, Suite 15c
Denver, Colorado 80211

Facility Name: Fort St. Vrain Nuclear Generating Station (FSV)

Inspection At: FSV, Platteville, Colorado


Inspection Conducted: November 2-6, 1987

Inspector:


A. B. Earnest, Physical Security Specialist
Radiological Protection and Safeguards Branch

12/30/87
Date

Approved:


L. A. Yandell, Chief, Radiological Protection
and Safeguards Branch

12/31/87
Date

Inspection Summary

Inspection Conducted November 2-6, 1987 (Report 50-267/87-29)

Areas Inspected: Routine, unannounced inspection of the licensee's management effectiveness, security organization, security audits, record and reports, testing and maintenance, physical barriers - vital areas (VA), security system power supply, access control - packages, access control - vehicles, access control - personnel, detection aids - VA, alarm stations, communications, training and qualifications, and compensatory measures.

Results: Within the areas inspected, two violations were identified (inadequate compensatory measures, paragraph 3; inadequate access control - personnel, paragraph 4).

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.