

DMB COPY

JAN 0 5 1988

Beloit Memorial Hospital
ATTN: Mr. M. E. Rindler
President
1969 West Hart Road
Beloit, WI 53511

License No. 48-11281-02
License No. 48-13109-01

34-3474
34-557

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. W. Patterson of this office on December 23, 1987, of activities authorized by NRC Byproduct Material Licenses No. 48-11281-01 and No. 48-13109-01, and to the discussion of our findings with John Babbs, M.D., Gordin Chalk and Paul Peterson at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

With respect to Items D and I, identified during our March 19, 1984 inspection, this inspection showed that action had been taken to correct the identified violations and to prevent recurrence. Consequently, we have no further questions regarding this matter at this time.


During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the enclosed Appendix. A written response is required.

No violations were identified for License No. 48-13109-01.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,


D. G. Wiedeman, Chief
Nuclear Materials Safety
Section 1

8801130214 880105
REG3 LIC30
48-11281-02 PDR

Enclosure: Notice of
Violation

cc w/enclosure:
DCD/DCB (RIDS)

RIII

Patterson/ib

YES
RIII

Wiedeman
1/5/88

IE07
11