DMB COPY

JAN 0 4 1988

License No. 24-20353-01

William A. Lemire, Associates, Ltd. ATTN: Mr. William A. Lemire President P.O. Box 2038 Maryland Heights, MO 63043

Gentlemen:

This refers to the routine safety inspection conducted by James W. Patterson of this office on December 2, 1987, of activities authorized by NRC Byproduct Material License No. 24-20353-01 and to the telephone discussion about our findings with you on December 28, 1987, at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

The responses directed by this letter and the accompanying Notice (Notice) are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Robert E. Burgin, Chief Nuclear Materials Safety Section 2

Enclosure: Notice of Violation

cc w/enclosure: DCD/DCB (RIDS)

8801130225 880104 REG3 LIC30 24-20353-01 PDF PDR

bn/crr