

Log # TXX-88039 File # 10110

903.9

Ref. # 10CFR50.55(e)

William G. Counsil Executive Vice President

January 6, 1988

C. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM FLECTRIC STATION (CPSES)

DOLKET NO. 50-445

ELECTRICAL RACEWAY SUPPORT SYSTEM SDAR: CP-85-31 (INTERIM REPORT)

Gentlemen:

On December 5, 1986, by our letter logged TXX-6138, we notified you of a deficiency involving the Unit 1 Class 1E Electrical Raceway Support System which we deemed reportable under the provisions of 10CFR50.55(e). This is an interim report submitted to status corrective actions implemented to date. Our latest report, logged TXX-6864 was submitted October 16, 1987.

This deficiency involves the installation of Separation Barrier Material (SBM) and Radiant Energy Shield (RES) material on Unit 1 Class 1E Electrical Conduit Raceways without engineering interdisciplinary design review of the proposed support system change. All SBM will be removed from power cables/raceway except where designated for RES purposes in the containment buildings (via NCR CE-87-4577). The modification and addition of supports affected by the installation of RES is continuing.

Based on our current projected schedule, our next report for this issue will be submitted no later than June 1, 1988.

Very truly yours,

W. G. Counsic

W. G. Counsil

By:

J. S. Marshall

Supervisor, Generic Licensing

DAR/grr

8801130240 880106 PDR ADOCK 05000445

c - Mr. R. D. Martin, Region IV Resident Inspectors, CPSES (3)

I 227