NUG 0 2 1994

1 Pullinger

JEON

Docket No. 50-346

Centerior Service Company ATTN: Mr. John P. Stetz Vice President Nuclear - Davis-Besse c/o Toledo Edison Company 300 Madison Avenue Toledo, OH 43652

Dear Mr. Stetz:

SUBJECT: ROUTINE RESIDENT INSPECTION AT DAVIS-BESSE (50-346/94006(DRP))

This refers to the inspection conducted by Messrs. S. Stasek, J. M. Shine, and T. M. Tongue of this office on June 3, 1994, through July 22, 1994. The inspection included a review of activities authorized for your Davis-Besse Nuclear Power Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of particular concern because it involves instances where your administrative procedures were not adequately adhered to. Procedural adherence problems at Davis-Besse have been previously identified in recent inspection reports and continue to be of concern to the NRC.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosed inspection report and your responses to this letter will be placed in the NRC Public Document Room.

3100032 940802 ADOCK 05000346 PDR

020004

Centerior Service Company

.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL-96-511.

2

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. D. Lanksbury, Chief Reactor Projects Section 3B

Enclosures: 1. Notice of Violation 2. Inspection Report No. 50-346/94006(DRP) cc w/enclosure: J. K. Wood, Plant Manager W. T. O'Connor, Manager Regulatory Affairs D. C. Shelton, Senior Vice President - Nuclear OC/LFDCB Resident Inspector, RIII LPM, NRR State Liaison Officer, State of Ohio Robert E. Owen, Ohio Department of Health A. Grandjean, State of Ohio, Public Utilities Commission S. Stein, SRS

bcc: PUBLIC (IE01)

RIII 971 J. McCormick-Barger (para. 1.d and 5.a) 8/2/94 \$ 5.6 (para. 5.10) RIII RIII RIII Creed Olteanu RIII RIIII RIII RIII RIII RI

RIII ROL Lanksbury 8/2/24



UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 801 WARRENVILLE ROAD LISLE, ILLINOIS 60532-4351

AUG 0 2 1994

Docket No. 50-346

Centerior Service Company ATTN: Mr. John P. Stetz Vice President Nuclear - Davis-Besse c/o Toledo Edison Company 300 Madison Avenue Toledo, OH 43652

Dear Mr. Stetz:

SUBJECT: ROUTINE RESIDENT INSPECTION AT DAVIS-BESSE (50-346/94006(DRP))

This refers to the inspection conducted by Messrs. S. Stasek, J. M. Shine, and T. M. Tongue of this office on June 3, 1994, through July 22, 1994. The inspection included a review of activities authorized for your Davis-Besse Nuclear Power Station. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation is of particular concern because it involves instances where your administrative procedures were not adequately adhered to. Procedural adherence problems at Davis-Besse have been previously identified in recent inspection reports and continue to be of concern to the NRC.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosed inspection report and your responses to this letter will be placed in the NRC Public Document Room.

Centerior Service Company

. AUG 0 2 1994

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL-96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. D. Lanksbury, Chief Reactor Projects Section 3B

Enclosures:

- Notice of Violation
 Inspection Report No.
 - 50-346/94006(DRP)

cc w/enclosure: J. K. Wood, Plant Manager W. T. O'Connor, Manager Regulatory Affairs D. C. Shelton, Senior Vice President - Nuclear OC/LFDCB Resident Inspector, RIII LPM. NRR State Liaison Officer, State of Ohio Robert E. Owen, Ohio Department of Health A. Grandjean, State of Ohio, Public Utilities Commission S. Stein, SRS