

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

TELEPHONE  
(704) 373-4531

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

February 16, 1988


U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: McGuire Nuclear Station  
Docket No. 50-369  
Revised Licensee Event Report 369/87-20-01

Gentlemen:

Pursuant to 10CFR 50.73 Sections (a)(1) and (d), attached is revised Licensee Event Report 369/87-20-01 concerning Residual Heat Removal Pump 1B being inoperable unknowingly for eight days due to a flow instrument which controls the pump recirculation valve being left isolated after repairs. The revised report is a result of additional analysis of this event and is to correct a wording error in the abstract, provide an expanded safety analysis, and an additional planned corrective action. Revisions are indicated by change bars in the right margin. This report is being submitted in accordance with 10CFR 50.73(a)(2)(i)(B), and is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

SEL/225/jgc

Attachment

xc: Dr. J. Nelson Grace  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., NW, Suite 2900  
Atlanta, GA 30323

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, GA 30339

M&M Nuclear Consultants  
1221 Avenue of the Americas  
New York, NY 10020

American Nuclear Insurers  
c/o Dottie Sherman, ANI Library  
The Exchange, Suite 245  
270 Farmington Avenue  
Farmington, CT 06032

Mr. Darl Hood  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555

Mr. W.T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

8802180171 880216  
PDR ADOCK 05000369  
S PDR

FE22  
1/1