U.S. NUCLEAR REGULATORY COMMISSION

10 CFR 2.201

SAFETY INSPECTION

				Page 1 of
1. LICENSEE Testing Technologies Woodbridge, VA		2. REGIONAL OFFICE REGION II U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323		
3. DOCKET NUMBER(S)	4. LICENSE NUMBER	(S)	5. DATE OF INSPECTION	
030 - 306 57	45-25007-0	120	619-10197	
LICENSEE: The inspection was an examination of the a Regulatory Commission (NRC) rules and reprocedures and representative records, interfollows:	gulations and the condition rviews with personnel, and	ns of your license. The inspect observations by the inspect	ention consisted of selective	examinations of
2. The inspector also verified the ste questions on those actions at this 3. During this inspection certain of y NOTICE OF VIOLATION, which is	time.	below or attached, were in	violation of NRC requirement	
A			was not properly	posted to
indicate the presence of a			. 10 CFR 20.203	(b),(c),(d),(e) or 34.42.
B			of sealed sources	s were not
performed at the proper fre	quencies. 10 CFR	or License C	ondition Number	*
C. Records of			were not prope	rly maintained.
10 CFR	or License Condition	Number		
D. Documents were not proper	rly posted or otherwise ma	de available. 10 CFR 19.11.		
E. Reports or notification of			were not made in	n accordance with
10 CFR	or License Condition I	Number		
F.				
				imininin —
i hereby state that, within 30 days, the action above. This statement of corrective actions unless required by the NRC.				
SIGNATURE - LICENSEE 9707230350 970610 PDR ADDCK 03030657 C PDR	DATE	SIGNATURE NRC INSPE	ECTOR de la companya della companya della companya della companya de la companya della companya	DATE 6/97 34

NRC FORM 591 Part 1 (7-91)

JE07