## SAFEGUARDS INFORMATION



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA STREET, N.W., SUITE 2900 ATLANTA, GEORGIA 30323-0199

Report Nos. 50-338/94-29 and 50-339/94-29		
Licensee: Virginia Electric and Power Company Glen Allen, VA 23060		
Docket Nos. 50-338 and 50-339	License Nos.	NPF-4 and NPF-7
Facility Name: North Anna Power Station Units 1	and 2	
Inspection Conducted: November 28 - December 2,		
Inspector: W. J. Tobin, Senior Safeguards Inspecto	r	12/29/94 Date Signed
Approved by: A. A. A. D. R. McGuire, Chief Safeguards Section	de Pranch	12/29/94 Date Signed
Nuclear Materials Safety and Safeguards Branch Division of Radiation Safety and Safeguards		

## SUMMARY

Scope:

This routine, unannounced inspection was conducted in the areas of the Physical Security Program for Power Reactors. Specific areas inspected were Audits, Compensatory Measures, and Training and Power Supply. A Fitness For Duty event was also reviewed. The inspector evaluated the licensee's corrective action to a prior violation in addition to an Unresolved Item.

## Results:

9501050079 941229

PDR

ADOCK 05000338

In the areas inspected, violations or deviations were not identified. The licensee's most recent audit of the Security Program was thorough and intensive. Compensatory measures are kept to a minimum. Training appeared appropriate and Power Supply was adequately being addressed. The prior violation relative to control of Safeguards Information is "closed," as was the Unresolved Item relative to devitalization.

The Fitness For Duty incident reported by the licensee to the NRC regarding apparently falsified records will receive further NRC evaluation and will be tracked as an Unresolved Item (50-338 and 339/94-29-01).

SAFEGUARDS INFORMATION

Document transmitted herewith contains sensitive unclassified information. When separated from enclosures, this document is decontrolled.