

DUKE POWER COMPANY

P.O. BOX 33189  
CHARLOTTE, N.C. 28242

HAL B. TUCKER  
VICE PRESIDENT  
NUCLEAR PRODUCTION

TELEPHONE  
(704) 373-531

July 1, 1988


U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D. C. 20555

Subject: Catawba Nuclear Station  
Docket Nos. 50-413 and 50-414  
Steam Generator Tube Rupture Analysis

Dear Sir:

In my letter of May 18, 1988 concerning the same subject, it was indicated demonstration runs would be performed to ensure analysis assumptions were correct. The results of this effort were to be submitted by July 1, 1988. These demonstration runs along with a modification to the Unit 2 D-5 Steam Generators have resulted in a delay in finalizing the demonstration runs and analyses. The results will be provided by November 3, 1988.

Very truly yours,



Hal E. Tucker

PGL/43/sbn

cc: Dr. J. Nelson Grace, Regional Administration  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, NW, Suite 2900  
Atlanta, Georgia 30323

Mr. P. K. Van Doorn  
NRC Resident Inspector  
Catawba Nuclear Station

Dr. K. Jabhour  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

A001  
||

8807130177 880701  
PDR ADOCK 05000413  
P PDC