ENCLOSURE B

10 CFR 50.59 REPORT

Period from January 1, 1986 through June 7, 1987

Revised Item

SM 86-055

Shoreham Nuclear Power Station Docket No. 50-322 March 1988

8803300386 880328 PDR ADOCK 05000322 R DCD

•

SM 86-055 (DOP 86-094)

Description of Change:*

Added two (2) 42" diameter manways and modified one (1) 24" diffuser port to provide access into the offshore diffuser of the Main Condenser Circulating Water Discharge System for inspection, cleaning, and maintenance purposes.

Summary:

- I. No. No safety related equipment is involved in this change.
- II. No. Modification does not interface with safety related equipment.
- III. No. See I and II above. There is no impact upon plant conditions or safety related analyses by this modification.

*NOTE: This item revises the report of the same number (SM 86-055) previously reported under SNRC-1397 of December 4, 1987, for the reporting period January 1, 1986 through June 7, 1987. The "Description of Change" is revised to show two (2) 42" diameter manways installed instead of four (4). All other statements under SM 86-055 remain unchanged.