

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority
Phipps Bend, Unit No. 1

License No. CPPR-162

Based on the NRC inspection August 7-9, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by 10 CFR 50, Appendix B, Criterion VI, and as implemented by the PSAR Paragraph 17.1A.6 and Table II of TVA "OEDC-QA Program Requirements Manual", measure shall assure that documents be reviewed and approved. Rockwell International "Quality Assurance Program Plan for Preservice and Inservice Inspection Programs", N001PP 100-017, Rev. C, paragraph numbers 11.2.1 and 15.2.1 require an approved inspection plan to be used.

Contrary to the above, on August 9, 1979, Rockwell International was inspecting the reactor pressure vessel in accordance with an informal inspection plan not approved by TVA.

This is an infraction.

7910250

529