

APR 07 1988

Docket No. 50-346

Toledo Edison Company
ATTN: Mr. Donald Shelton
Vice President
Nuclear
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to the special radiological controls team inspection conducted by Mr. D. E. Miller and others of this office on February 23-26 and March 7-11, 1988, of activities at Davis-Besse Nuclear Power Station, Unit 1, authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. L. Storz and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

IR06
//

Toledo Edison Company

2 APR 07 1988

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Original signed by W.D. Shafer

W. D. Shafer, Chief
Emergency Preparedness and
Radiological Protection Branch

Enclosure: Inspection Report
No. 50-346/88008(DRSS)

cc w/enclosure:
L. Storz, Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert M. Quillin, Ohio
Department of Health
State of Ohio, Public
Utilities Commission

RIII
Miller/jaw
Gregor
4-5-88

RIII
Grant
RWP
DeFayette
4/6

RIII
Kobowski
Staley

RIII
Lagg

RIII
Holtzman

40
RIII
Weil
4/6/88

RIII
Schuimacher
4/6/88