FORM N (3-7	NRC-591 775		U.S. NUCLEAR REGU	JLATORY COMMISSIC	
		INSPE	CTION FINDINGS AND I	LICENSEE ACKNOWLE	DGMENT
N 6 H	uclear 150 odskins	Welding East J		2. REGIONAL OFFICE U. S. Nucles Region III 799 Roosevel Glen Ellyn,	ar Regulatory Commission
3. 000	CKETNUMBER	1	4 LICENSE NUMBER	R(S)	8. DATE OF INSPECTION
6. INSI The in Comm	ussion's rules and	INGS examination of th d regulations and th	e activities conducted under y	The inspection consisted of an	radiation safety and to compliance with the radiation safety and to compliance with the resummations of procedures and repre- present to are as follows:
X	No items of i	noncompliance of	unsafe conditions were fo	und. 19 of	Mr.
The following items of noncompliance related to records, signs, and labels the found UL/VFA					
	A. Rooms or areas were not properly posted to indicate the presence of a HICP AND ALLON ARTA				
	B. Rooms or areas were not properly posted to indicate the presence of a HIGHMAN SATION AREA. 10 CFR 20.203(c) (1) or 34.42				
	C. Rooms or areas were not properly posted to indicate the presence of ACTIVITY ARFA. 10 CFR 20.203(d)				
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)				
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)				
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)				
	G. Form NRC-3 was not properly posted. 10 CFR 20.206(c)				
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(5)				
	1. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)				
	 Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51 				
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)				
	M. Utilization logs were not maintained. 10 CFR 34.27				
	N. Records of radiation survey lastrument calibration were not maintained. 10 CFR 34.24				
	er en				
			Ways	A lla	-L.
			ed and I understand the i I within the next 30 days		listed above. The items of
	81032	250551			POOR GRIGINAL
	(De	ate)	and an and a second	(Licensee Representat	tine - Title or Position)

辨問題

编制出于2性

和出版

STATED AND THEFT IS NOT