SAFEGUARDS INFORMATION

JUL 1 2 1988

Docket No. 50-10 Docket No. 50-237 Docket No. 50-249

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the reactive safeguards inspection conducted by Mr. D. E. Funk, Jr. of this office on June 28 and 30, 1988, of activities at Dresden Nuclear Power Station, Units 1, 2, and 3, authorized by NRC Operating Licenses No. DPR-02, No. DPR-19, and No. DPR-25 and to the discussion of our findings with Mr. J. Mayer and members of his staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the enclosed Notice. The inspection showed that action had been taken to correct the identified violation and to prevent recurrence. Our understanding of your corrective actions is described in Paragraph 5 of the enclosed inspection report. Consequently, no reply to the violation is required. Inspection results also identified one other violation of the security plan which is addressed in Section 4 of the report details. This violation meets the criteria of 10 CFR Part 2, Appendix C, Section V.G. as licensee identified and therefore, a separate Notice of Violation will not be issued.

Areas examined during this inspection concern a subject matter which is exempt from disclosure according to Part 73, Title 10, Code of Federal Regulations, Section 73.21(c)(2). This information must be handled and protected in accordance with the provisions of 10 CFR 73.21. Consequently, the enclosure to this letter and our report of this inspection will not be placed in the NRC Public Document Room.

8807260219 880712 PDR ADDCK 0500010 Q PNU IEO4

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled

Commonwealth Edison Company

2

JUL 1 2 1988

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Bruce S. Mallett, Ph.D., Chief Nuclear Material Safety and Safeguards Branch

Enclosures:

1. Notice of Violation

2. Inspection Reports

No. 50-10/88004(DRSS); No. 50-237/88016(DRSS); No. 50-249/88017(DRSS)

(UNCLASSIFIED SAFEGUARDS INFORMATION)

cc w/enclosures:
H. Bliss, Nuclear
Licensing Manager
J. Eenigenburg, Plant Manager
NRR/DRIS/SGB
NRR/DRIS/S1B
NRR/DLPO/FEB

cc w/enclosures, w/o
 UNCLASSIFIED SAFEGUARDS
 INFORMATION:
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Richard Hubbard
J. W. McCaffrey, Chief, Public
Utilities Division

Funkyims

RIII

RIII Ring May 18th

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled