

official

APR 07 1988

Docket Nos. 50-413, 50-414
License Nos. NPF-35, NPF-52

Duke Power Company
ATTN: Mr. H. B. Tucker, Vice President
Nuclear Production Department
422 South Church Street
Charlotte, NC 28242

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-413/88-12 AND 50-414/88-12

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by C. H. Bassett on February 22-26, 1988. The inspection included a review of activities authorized for your Catawba facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The inspection findings indicate that certain activities appeared to violate NRC requirements. However, because all of the criteria for categorization of licensee-identified violations were met, the violation is not being cited. The details pertaining to the licensee-identified violation are described in the enclosed Inspection Report.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

ORIGINAL SIGNED BY
DOUGLAS M. COLLINS
Douglas M. Collins, Chief
Emergency Preparedness and
Radiological Protection Branch
Division of Radiation Safety
and Safeguards

Enclosure:
Inspection Report

cc w/encl:
T. B. Owens, Station Manager

8804150392 880407
PDR ADOCK 05000413
Q DCD

11
IE06

bcc w/encl:
K. N. Jabbour, NRR
NRC Resident Inspector
DRS Technical Assistant
Document Control Desk
State of South Carolina
Document Control Desk

RII
CB
CBassett
4/4/88

RII
CH
CHosey
4/4/88

RII
TP
TPeebles
4/5/88