July 15, 1988

Docket Nos. 50-338, 50-339 License Nos. NPF-4, NPF-7

Virginic Electric and Power Company ATTN: Mr. D. S. Cruden, Vice President, Nuclear Operations P. O. Boc 26666 Richmond, VA 23261

Gentlemen:

SUBJECT: NOTICE OF VIOLATION


(NRC INSPECTION REPORT NOS. 50-338/88-06 AND 50-339/88-06)

This refers to the Nuclear Regulatory Commission (NRC) Operational Performance Assessment (OPA) conducted by L. Watson and team on March 28 - April 1 and April 11 - 15, 1988, at your North Anna facility. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed inspection report.

The OPA was a performance based team assessment which identified significant operational strengths and weaknesses, rather than a compliance oriented inspection. The inspection included an evaluation of the effectiveness of various plant groups including Operations, Maintenance, Quality Assurance, Engineering, and Training, in supporting safe plant operations. Particular attention was directed to assessing management awareness of, involvement in, and support of safe plant operations.

A number of notable strengths and improvement efforts were identified in your programs and are discussed in the enclosed report. However, during the course of the inspection, certain activities were noted which appeared to violate NRC requirements. The violation, references to pertinent requirements, and elements to be included in your response are described in the enclosed Notice of Violation. There is also an unresolved item identified in the inspection report which will be pursued during future inspections.

We direct your attention to those areas identified as weaknesses during the inspection. The more significant areas where improvements were needed included the periodic calibration of control room instrumentation; maintaining and using maintenance history files; the generation, review and control of procedure changes; the trending of deficiencies; and, identification of root cause of equipment deficiencies. We encourage prompt management attention to these areas. We also support your actions to improve areas previously targeted by you for enhancement and encourage aggressive implementation of these improvements particularly in the areas of post maintenance testing and procedural upgrades.



In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

The responses :rected by this letter and its enclosure are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96-511.

Should you have any questions concerning this letter, please contact us.

Sincerely,

A NELSON GRACE

J. Nelson Grace Regional Administrator

Enclosures:

Notice of Violation
 NRC Inspection Report

cc w/encls:

G. E. Kane, Station Manager

N. E. Hardwick, Manager - Nuclear Programs and Licensing

bcc w/encls:

W. Troskowski, EDO

H. Berkow, NRR

L. Engle, NRR

B. Grimes, NRR

G. Lainas, NRR

L. Reyes, DRP

E. Merschoff, DRS

B. Wilson, DRP

06/3/88

NRC Resident Inspector DRS Technical Assistant Document Control Desk Commonwealth of Virginia

RII RII
LWatson:ser MShymlock
06/14/88 06/1/88

RII RII
RII
RII
RII
RII

08/14/88

CJultan 06/27/88

MErnst 06/ /88 RII

FCantrell 06/22/88