Telephone (412) 393-6000



Nuclear Group P.O. Box 4 Shippingport, PA 15077-0004

April 18, 1988

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Reference: Beaver Valley Power Station, Unit No. 1 Docket No. 50-334, License No. DPR-66 Second Ten-Year Inservice Inspection Interval Program

Gentlemen:

In our letter dated July 28, 1987, we stated that due to the effort being expended to complete the first interval inservice inspections (ISI) during the sixth refueling outage, we did not anticipate submittal of the second ten-year ISI Program until April 30, 1988. Due to the effort being expended to complete the following tasks we cannot complete the above in the specified time.

- Completion of the Pre-Service Inspection report for Beaver Valley Unit 2
- Completion of the reconciled Ten-Year plan for Beaver Valley Unit
- Completion of the ninety day report for Beaver Valley Unit 1, Sixth Refueling Outage
- Completion of the first Ten-Year plan for Beaver Valley Unit 2

Therefore, we now anticipate submittal of the second ten-year ISI Program for Beaver Valley Unit 1 by October 15, 1988.

If there are any questions concerning this matter, please contact my office.

Very truly yours,

Sieber

Act

10

Vice President Nuclear Group

cc: Mr. J. Beall, Sr. Resident Inspector Mr. W. T. Russell, NRC Region I Administrator Mr. P. Tam, Project Manager Director, Safety Evaluation & Control (VEPCO)

8805030166 80418 PDR ADOCK 05000334 P 8 PDR