




DRESSER INDUSTRIES, INC. P. O. BOX 1407, HOUSTON, TEXAS 77001 713/972-6011 TWX: 910-881-3708

November 11, 1982

Mr. John T. Collins
Regional Administrator
U. S. NRC Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012



Dear Mr. Collins:

The Dresser Atlas Base at Elk City, Oklahoma has constructed a new Radioactive Materials Storage Bunker as per the attached sketches.

Please contact me in Houston if you have any questions or require additional information.

Sincerely,

E. D. Mott

E. D. Mott Supervisor
Radiological Safety & Health

cc: Mr. Mark S. Coleman
Deputy Commissioner for Environmental Health
State Department of Health
N. E. 10th and Stone Wall Streets
P. O. Box 53551
Oklahoma City, OK 73152

cc: N. F. Ruddy
B. D. Dudley
D. M. Rowe
NRC File
OK File

EDM:ar

Attachment

8602120145 850528
REG4 LIC30
42-02964-01 PDR

Applicant	867031
Check No.	#110-5A
Amount/Fee Category	Amendment
Type of Fee	3/31/83
Date Check Rec'd.	Brown
Received By	

RECEIVED BY LFME	
Date	1/31/83
Log	Jan 9 Audit
By	Brown
Orig To	
Action Compl.	3/21/83


COPIES SENT TO OFF. OF
INSPECTION AND ENFORCEMENT

1.16.34

ELK CITY, OK. 9-8-82
Highway 6 and Robinson Place

South Fence

New Radioactive
Materials Storage



Lub Rack

Wash Bay

Mechanic's Bay

Bay #2

Old RAM
Storage


Bay #1

Offices


Gate

East Fence

West Fence



Pipes 48" Below
Ground



Radioactive Materials Storage
E/H City, OK. 11-1-82

DRESSER

3742

Dresser Atlas

DIVISION OF DRESSER INDUSTRIES, INC.

10201 WESTHEIMER, P. O. BOX 1407, HOUSTON, TEXAS 77001 • 713 784-6011

October 11, 1978

Mr. Frederick Combs
U. S. Nuclear Regulatory Commission
Radioisotopes Licensing Branch
Division of Fuel Cycle and
Material Safety
Washington, D. C. 20555

Gentlemen:

This letter is in response to the request by Dresser Atlas for formal notification of the closing of a facility. The attached drawings of the Dresser Atlas Columbus Junction, Iowa location, details the radiation inspection conducted prior to our closing. There was no radiation contamination left in the facility. During the time Dresser Atlas maintained this facility, there were no unsealed radioisotopes used in Iowa. All sources of radiation used were special form encapsulation.

If the enclosed drawings do not meet the requirements, please contact me for further correspondence.

Sincerely yours,

David Norman

David Norman
Radiation Safety Coordinator

DN:js
Enclosures


cc: Retired facility file
Location File

COPIES SENT TO OFF. OF
INSPECTION AND ENFORCEMENT

8405240044

308

- - DRHWING FOR SHOP, COLUMBUS JCT, 10WH, 116 N MAIN ST.




TO DOCK AREA

COLUMBUS JCT

EACH SMALL SQUARE = 4"

3742

SIGN
8" X 10"
CAUTION
READING
AREA



CONSTRUCTION
CONCRETE BLOCKS WITH
AIR SPACES FILLED WITH SOIL

ALL READINGS WERE TAKEN
AFTER SOURCES WERE
REMOVED.

INSIDE OF BUNKER LESS THAN 0.2 METER
1 FT FROM BUNKER " " 0.2 METER
10 FT FROM BUNKER " " 0.2 METER

SURVEYING WAS DONE WITH
BETA SHIELD OF PROBE "OPEN"

Carl S. Wilfinger

DRAWING OF BUNKER
LOCATED AT COLUMBUS ST, 10 WA
716 NORTH MAIN ST.

1" = 1 FT.

DRESSER

Dresser Atlas

DIVISION OF DRESSER INDUSTRIES, INC.

10201 WESTHEIMER, P. O. BOX 1407, HOUSTON, TEXAS 77001 • 713 784-6011

May 10, 1978

Mr. Joseph M. Brown, Jr.
Radioisotopes Licensing Branch
Division of Fuel Cycle and
Material Safety
United States Nuclear Regulatory Commission
Washington, D.C. 20555

License No. 42-02964-01
Control No. 90171


Dear Mr. Brown:

Dresser Atlas has closed their Columbus Junction, Iowa District Office at 116 North Main Street.

We have not given up possession of this office as yet. All radioactive materials have been moved out and a survey has shown the area to be clean and free from any contamination. This survey was conducted with a Ludlum Model II meter. No readings above normal background were observed.

Please remove this address from our license application. If any further action is necessary, please let us know.

Sincerely,



D. M. Muir
Manager of Health and Safety

DMM:fd


cc: Region IV USNRC
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

COPIES SENT TO OFF. OF
INSPECTION AND ENFORCEMENT

8405240013

288

Petroleum Services Group
Inter-Office Correspondence

DRESSER

To Jack Lee
From Carlos D. McGregor
Copy to Dave Muir ✓
Wayne Denney
File

Date May 5, 1978

Subject Survey Reading -
Columbus Junction, Iowa

Having completed the moving of equipment from Columbus Junction, Iowa, a survey was run to check for radio-active contamination. NO readings were found to be above normal background.

CM/dn

Carlos D. McGregor