APR 2 7 1988

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the special safety inspection conducted by Mr. M. J. Farber of this office from April 12 through April 14, 1988, of allegations regarding certain activities at the Davis-Besse Nuclear Power Station authorized by Facility Operating License No. NPF-3 and to the discussion of our findings with Mr. L. F. Storz and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.


Sincerely,

R. C. Knop, Chief

Reactor Projects Branch 3


Enclosure: Inspection Report No. 50-346/88013(DRP)


|--|



Gu Vdemond







## Toledo Edison Company

## Distribution

cc w/enclosure: L. Storz, Plant Manger DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Harold W. Kohn, Ohio EPA James W. Harris, State of Ohio Robert M. Quillin, Ohio Department of Health State of Ohio, Public Utilities Commission Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President Nuclear Edison Plaza 300 Madison Avenue Toledo, OH 43652

Gentlemen:

This refers to the special safety inspection conducted by Mr. M. J. Farber of this office from April 12 through April 14, 1988, of allegations regarding certain activities at the Davis-Besse Nuclear Power Station authorized by Facility Cperating License No. NPF-3 and to the discussion of our findings with Mr. L. F. Storz and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observation1, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.


We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. C. Knop, Chief

R. C. Knop, Chief V Reactor Projects Branch 3

Enclosure: Inspection Report No. 50-346/88013(DRP)



## Toledo Edison Company

## Distribution

cc w/enclosure: L. Storz, Plant Manger DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Harold W. Kohn, Ohio EPA James W. Harris, State of Ohio Robert M. Quillin, Ohio Department of Health State of Ohio, Public Utilities Commission