

NOTE TO: License Fee Management Branch, ADM

FROM: Region 3

SUBJECT: VOIDED APPLICATION

Control Number 84184

Applicant Consumers Power Company

Date Voided 2/29/88

Reason for Void did not respond to

within 30 days to deficiency
telephone call

Signature Loren J. Hunter

Attachment:
Application

8805060156 880229
REG3 LIC30
21-18784-01 PDR

OK LFM B

ML 86

CONVERSATION RECORD

TIME 8:30

DATE 2-29-88

TYPE

☐ VISIT

☐ CONFERENCE

☒ TELEPHONE

☐ INCOMING

☒ OUTGOING

ROUTING

NAME/SYMBOL INT

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

ORGANIZATION (Office, dept., bureau, etc.)

TELEPHONE NO.

Tom Neal

Consumer Power Company

616-764-8913

SUBJECT

C/N 84184

SUMMARY

The licensee representative noted above was informed that we are voiding their request for an amendment (C/N referenced above) since they have not responded within the specified 30 days to our telephone request made on December 23, 1987 for additional information.

Further, the licensee representative was informed that we will hold the information previously submitted in their request for one year. If they wish to reactivate the request within that time, they may do so without being assessed additional fees by providing the requested information and referencing the control number listed above.

ACTION REQUIRED

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

DATE

LOREN HUETER

Loren Hueter

2-29-88

ACTION TAKEN

SIGNATURE

TITLE

DATE

CONVERSATION RECORD

TIME
9:30

DATE
12-23-87

TYPE

☐ VISIT

☐ CONFERENCE

☒ TELEPHONE

☐ INCOMING

☒ OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

Tom NEAL RSO

ORGANIZATION (Office, dept., bureau, etc.)

Consumers Power Company

TELEPHONE NO.

616-764-8913
x0595

SUBJECT

C/N 84184

ROUTING

NAME/SYMBOL

INT

SUMMARY

1. Tom stated reason for mailing address change to Colorado plant was intended and was because he, as RSO, was located there.
2. Although the proposed gas chromatograph is called "portable", Tom stated it will be used in a fixed location in a lab with fume hood for venting effluent from G.C. at the 135 West trail St. lab location in Jackson.
3. Tom was informed that application, ^{dated 9-18-87} for Amend to Lien 21-18784-01 was deficient in that it did not provide Model No. of detector cell nor could we find any services in approved source of device registry for the stated manufacturers, T Sierra Environmental Instruments. Requested Following
 1. Manufacturer or distributor under whom detector cell registered
 2. Registry No. for detector cell
 3. Date of issuance of Registry No.

ACTION REQUIRED

(over)

Letter Response in 30 days

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

DATE

Loren J. Hester

12-23-87

ACTION TAKEN

SIGNATURE

TITLE

DATE

4. Model Number of Detection cell
5. Type of foil in detector cell. Titanium tritide or scandium tritide?
6. Maximum activity on foil in one cell

Tom was also requested to provide above info in duplicate in 30 days and to reference control #.