

Duke Power Company  
P.O. Box 33198  
Charlotte, N.C. 28242

Hal B. Tucker  
Vice President  
Nuclear Production  
(704)373-4531



**DUKE POWER**

August 23, 1988

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 2  
Docket No. 50-370  
Licensee Event Report

Gentlemen:

Pursuant to 10CFR 50.73 Sections (a)(1) and (d), a Licensee Event Report concerning an inadvertent main feedwater isolation that occurred on July 24, 1988, was to have been submitted August 23, 1988. Please be advised that due to unresolved concerns, the report will be delayed and submitted September 6, 1988.

Should there be any questions, please contact S.E. LeRoy at (704) 373-6233.

Very truly yours,

Hal B. Tucker

SEL317/sel

Attachment

xc: Dr. J. Nelson Grace  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta St., NW, Suite 2900  
Atlanta, GA 30323

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, GA 30339

M&M Nuclear Consultants  
1221 Avenue of the Americas  
New York, NY 10020

American Nuclear Insurers  
c/o Dottie Sherman, ANI Library  
The Exchange, Suite 245  
270 Farmington Avenue  
Farmington, CT 06032

Mr. Darl Hood  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Reactor Regulation  
Washington, D.C. 20555

Mr. W.T. Orders  
NRC Resident Inspector  
McGuire Nuclear Station

8809060261 880823  
PDR ADOCK 05000370  
S PDC

JE22  
1/0