In Reply Refer To: Docket: 50-382

Louisiana Power & Light Company
ATTN: J. G. Dewease, Senior Vice President
Nuclear Operations
317 Baronne Street
New Orleans, Louisiana 70160

Dear Mr. Dewease,


This is to inform you that the material provided by the Waterford 3 facility for use in preparation of the October 25, 1988, license examinations was determined as not meeting the requirements of Enclosure 1 to the examination scheduling letter dated July 28, 1988. Specifically, the material was not bound and indexed as required by Item 1 and the paragraph following Item 16. The material was received in the regional office on August 22, 1988. Mr. Toth of the facility training staff was notified of these deficiencies on August 23, 1988. He located a duplicate set of material and committed to correcting the deficiencies and shipping the material to arrive by August 29, 1988. The original set of material was returned to the facility on August 24, 1988.

Material, which is not properly bound and indexed, can more than double the time required to develop an examination item. Current examiner manning levels and a rigorous examination schedule do not allow time for examiners to reformat facility examination material to make it more useful for examination development.

The Chief Examiner for the October 25, 1988 examination discussed alternate approaches to assembling examination preparation material prior to each scheduled examination with Mr. Toth. These included maintaining a full set of examination development material in the regional office for which the cognizant examiner would be placed on distribution for revisions and new material and would accept responsibility for maintaining the regional held set of material. This would eliminate many of the potential problems that can arise when examination preparation material is assembled anew for each examination.

RIV:RI* C:OLS*
SLMcCory JLPellet
/ /88 / /88
*previously concurred

D:DRS* JLMilhoan / /88 D: DRP C WCallan 1/2/88





Louisiana Power and Light Company Due to the early identification of the discrepancies in the examination preparation material and the responsiveness of the facility training department, the scheduled date for examination administration is not impacted. If you have any questions on this matter, please contact us. Sincerely, L. J. Callan, Director Division of Reactor Projects Louisiana Power & Light Company ATTN: G. E. Wuller, Onsite Licensing Coordinator P.O. Box B Killona, Louisiana 70066 Louisiana Power & Light Company ATTN: N. S. Carns, Plant Manager P.O. Box B Killona, Louisiana 70066

> Middle South Services ATTN: Mr. R. T. Lally P.O. Box 61000 New Orleans, Louisiana 70161

Louisiana Power & Light Company
ATTN: R. F. Burski, Acting Manager
Nuclear Safety and Regulatory
Affairs
317 Baronne Street
P.O. Box 60340
New Orleans, Louisiana 70160

R.P. Barkhurst, Vice President Nuclear Operations Louisiana Power and Light Co. New Orleans Public Service, Inc. 317 Barrone Street P.O. Box 60340 New Orleans, LA 70160

Charles Toth, Training Manager Louisiana Power and Light WF-3 Generating Station P.O. Box B Killona, LA 0066

Louisiana Radiation Control Program Director

bcc to DMB (IE42)
bcc distrib. by RIV:
RRI
Section Chief (DRP/A)
RPB-DRSS
Project Engineer, DRP/A
RIV File
DRS
W. Smith, SRI
S. McCrory

R. D. Martin, RA LFMB-Facilities Section MIS System RSTS Cperator D. Wigginton, NRR Project Manager D. Chamberlain, RPS A J. Pellet, OLS