



**Florida
Power**

CORPORATION
Crystal River Unit 3
Docket No. 50-302
Operating License No. DPR-72

September 22, 1998
3F0998-02

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555-0001

Subject: Licensee Event Report (LER) 50-302/98-009-00

Dear Sir:

Please find enclosed Licensee Event Report (LER) 50-302/98-009-00 which discusses a personnel error during troubleshooting activities on the Emergency Feedwater Initiation and Control (EFIC) System that caused a Main Steam Line Isolation (MSLI) and resulted in a manual reactor trip. This report is being submitted pursuant to 10CFR50.73(a)(2)(iv).

If you have any questions regarding this submittal, please contact Mr. Walter J. Pike, Manager, Nuclear Regulatory Compliance, at (352) 563-4988.

Sincerely,

C. G. Pardee
Director
Nuclear Plant Operations

CGP:dwh
Enclosure

xc: Regional Administrator, Region II
Senior Resident Inspector
NRR Project Manager

9809280172 980922
PDR ADOCK 05000302
S PDR

11
IE22