

In Reply Refer To:
Docket: 50-285/85-26

FEB 19 1986

Omaha Public Power District
ATTN: R. L. Andrews, Division Manager-
Nuclear Production
1623 Harney Street
Omaha, Nebraska 68102

Gentlemen:

This refers to the inspection conducted by Messrs. A. R. Johnson and D. E. Norman of this office during the period November 18-22, 1985, of activities authorized by NRC Operating License DPR-40 for Fort Calhoun Station, Unit 1 and to the discussions of our findings with you and other members of your staff at the conclusion of the inspection. Discussions with you at a meeting in Region IV, Arlington, Texas, on December 13, 1985, are also included.

Areas examined during the inspection included actions you have taken with regard to six previously identified apparent violations or unresolved items, and two open items, of NRC Inspection Report 50-285/85-09. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspectors. Four of these apparent violations remained open pending further licensee action and NRC review. One new unresolved item was identified regarding your apparent failure to take the appropriate corrective actions, associated with the premature need for repair of a safety-related motor, as a result of high inlet piping vibration.

Within the scope of the inspection, no violations or deviations were identified.

Our Confirmatory Action Letter (50-285/CAL 85-07), dated December 20, 1985, identified the corrective actions which, at that time, were yet to be completed in connection with the deficiencies identified in NRC Inspection Report 50-285/85-09. These corrective actions are discussed in detail in the enclosed inspection report. Based on our inspection activities and your letter dated January 11, 1986, we now consider the corrective actions in CAL 85-07 to be complete. As stated in our letter dated January 17, 1986, we plan additional followup on your corrective actions during further inspections.

Any potential enforcement actions associated with the apparent violations identified in NRC Inspection Report 50-285/85-09 will be transmitted to you under separate cover.

<i>RSB</i>	<i>RSB</i>	<i>RSB</i>	<i>RPSB</i>	<i>PSB</i>	<i>RPB</i>	<i>EO</i>
RIV:RSB/ES	RSB:ES	RSB:ES	RPSB	PSB	RPB	EO
AJohnson/tw	DNorman	REireland	DHunnicut	DHunter	JEGagivardo	DPowers
2/5/86	2/5/86	2/5/86	2/5/86	2/5/86	2/12/86	2/19/86

8602250167 860219
PDR ADDOCK 05000285
Q PDR

1501/1

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original Signed By

J. E. Gagliardo, Chief
Reactor Projects Branch

Enclosure:
Appendix - NRC Inspection Report
50-285/85-26

cc w/enclosure:
W. G. Gates, Manager
Fort Calhoun Station
P. O. Box 399
Fort Calhoun, Nebraska 68023

Harry H. Voigt, Esq.
LeBoeuf, Lamb, Leiby & MacRae
1333 New Hampshire Avenue, NW
Washington, DC 20036

Kansas Radiation Control Program Director

Nebraska Radiation Control Program Director

bcc to DMB (IE01)

bcc distrib. by RIV:

*RPB	*Resident Inspector
*R&SPB	*Section Chief (RPB/B)
*RIV File	DRSP
*RSB	A. Johnson
	D. Norman

R. D. Martin, RA
*MIS System
*RSIS Operator
G. Zech, IE
U. Potopovs, IE
R. Wilson, IE
D. Powers, EO

*w/766