




DEPARTMENT OF THE AIR FORCE
HEADQUARTERS UNITED STATES AIR FORCE
BOLLING AFB DC 20332-6188



REPLY TO AFOMS
ATTN OF: BROOKS AFB TEXAS 78235-5000

SCPR

23 AUG 1988

SUBJECT: Notice of Violation NRC Form 591 Submission; NRC license No 42-23539-01AF,
Docket Nos 30-28641/88-08 (USAF RAM Permit 04-10117-2AFP), 30 28641/88-09 (USAF
RAM Permit 04-09951-1AFP), and 30-28641/88-10 (USAF RAM permit 04-09951-5AFP)

TO:

USNRC
Region IV
ATTN: Mr. D. Blair Spitzberg
611 Ryan Plaza Drive, Suite 1000
ArlingtonTX 76011

1. Please reference your 16 Aug 1988 letter regarding two notices of violations at USAF radioactive material permittees at McClellan AFB California.
2. Attached are the signed NRC form 591s. The violation under USAF RAM Permit No 04-09951-1AFP was corrected at the time of the inspection and the violations noted under USAF permit 04-10117-2AFP will be corrected within the 30 day time period. Please note that paragraph 3H of the NRC form 591 regarding the failure to conduct leak tests under condition 26.A.(2) of USAF RAM Permit 04-10117-2AFP should have referenced condition 25.A.(2).
3. Any questions or comments regarding the above should be directed to this office at commercial phone number 512 536-3331, or in writing.

Lawrence Donovan

LAWRENCE DONOVAN, Major, USAF, BSC
USAF Radioisotope Committee
Office of the Surgeon General

2 Atch

1. NRC Form 591, Docket 030-22419
2. NRC Form 591, Docket 030-22509

8809070097 880823
REG4 LIC30
04-10117-01AFP PNU

IC-88-751

11
IF-07