

Log # TXX-4699
File # 10110
903.10


TEXAS UTILITIES GENERATING COMPANY
SKYWAY TOWER • 400 NORTH OLIVE STREET, L.B. 81 • DALLAS, TEXAS 75201

February 12, 1986

WILLIAM G. COUNSIL
EXECUTIVE VICE PRESIDENT

Mr. Eric H. Johnson, Acting Director
Division of Reactor Safety and Projects
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76012

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION
DOCKET NO. 50-446
EQUIPMENT CONDUIT INTERFACE
SDAR: CP-85-39



Dear Mr. Johnson:

On September 18, 1985, we verbally notified your Mr. T. Westerman of a deficiency involving the installation of conduit to equipment which may not be as specified per design documents. This is an interim report of a potentially reportable item under the provisions of 10CFR50.55(e). We have submitted interim reports logged TXX-4589 and TXX-4615, dated October 10, 1985, and November 7, 1985, respectively. This issue has been expanded in scope to review flexibility problems associated with the equipment and raceway interface.

We are continuing our evaluation and anticipate completion of our final report by May 23, 1986.

Very truly yours,

A handwritten signature in cursive script that reads "W. G. Council".

W. G. Council

JCH/arm

c - NRC Region IV (0 + 1 copy)

Director, Inspection & Enforcement (15 copies)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

86-144

A DIVISION OF TEXAS UTILITIES ELECTRIC COMPANY
8602250343 860212
PDR ADDOCK 05000446
S PDR

10
IE-27