



Log # TXX-98217
File # 10010.1
916
Ref. # 10CFR50.55a

C. Lance Terry
Senior Vice President
& Principal Nuclear Officer

September 25, 1998

Mr. E. W. Merschhoff, Regional Administrator
U. S. Nuclear Regulatory Commission, Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION -UNIT 1
DOCKET NO. 50-445
UNIT 1 SIXTH REFUELING OUTAGE
STEAM GENERATOR INSERVICE INSPECTION TUBE PLUGGING
SPECIAL REPORT NO. 1-SR-98-002-01

REF: 1) TU Electric letter logged TXX-98117, from Mr. C. Lance Terry, to the NRC dated April 22, 1998

Supplement 1 to the subject report is being issued to correct typographical errors noted during a review of the previously issued report via Reference 1.

The initial report stated that, "[P]rior to operation, 140 tubes in each steam generator were expanded at the B and D baffle plate to reduce wear. TU Electric has removed all known defective tubes from service." The total number of tubes that were expanded at the B and D baffle was 124 (please refer to Attachment 2, page 2 of 2 of Ref. 1).

Additionally, Attachment 3 of Ref. 1 on page 8 of 8 stated that the tube in row 3 column 30 was plugged. The correct location of the plugged tube was row 2 column 30.

9809290152 980925
PDR ADOCK 05000445
P PDR

10001

16
A047

If there are any questions, please contact Obaid Bhatti at (254) 897-5839 to coordinate this effort. This communication contains no new licensing basis commitments regarding CPSES Units 1 and 2.

Sincerely,

C. L. Terry

C. L. Terry

By: *Roger D. Walker*
Roger D. Walker
Regulatory Affairs Manager

OB/ob

cc: NRC Document Control Desk
Mr. J. I. Tapia, Region IV
Mr. T. J. Polich, NRR
Mr. G. Bynog, TDLR
Resident Inspectors, CPSES