

1265
05 MAY 1988

Docket Nos. 030-00767
030-08144

License Nos. 20-02245-03
20-02245-04

Clark University
ATTN: John Brink, Ph.D.
Radiation Safety Officer
950 Main Street
Worcester, Massachusetts 01610

Gentlemen:

Subject: Routine Inspection No. 88-001

On November 23 and 25, 1987 and February 9, 1988, Steven Courtemanche of this office conducted a routine safety inspection at the above address of activities authorized by the above listed NRC licenses. The inspection was an examination of your licensed activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selective examination of representative records. The findings of the inspection were discussed with yourself at the conclusion of the inspection. This also refers to the telephone conversation on February 19, 1987 between yourself and Mr. Courtemanche.

Based on the results of this inspection, it appears that your activities were not conducted in full compliance with NRC requirements. A Notice of Violation is enclosed as Appendix A and categorizes each violation by severity level in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy). You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Based on the telephone conversation on February 19, 1988, we understand that the survey meters used for radiation surveys will be calibrated on an annual frequency by the manufacturer or by an individual licensed by the NRC to calibrate survey meters. Please confirm our understanding with the reply to this letter.

8805100361 880505
REG1 LIC30
20-02245-04 DCD

OFFICIAL RECORD COPY

ML DL CLARK UNIV - 0001.0.0
05/02/88

11
IE-07

RETURN ORIGINAL TO
REGION I

05 MAY 1988

Clark University

2

Item A in the Notice of Violation enclosed with this letter was identified during a previous inspection of your licensed activities and documented in a Notice of Violation enclosed with our letter dated November 13, 1984. From this inspection, it appears that your corrective actions were not effective since this item has recurred. Recurrent and uncorrected violations are given additional weight in the consideration and selection of appropriate enforcement action. Therefore, in your response to this letter, you should give particular attention to those actions taken or planned to ensure that identified items of noncompliance will be completely corrected and will not recur.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:
John D. Kinneman

John D. Kinneman, Chief
Nuclear Materials Safety Section B
Division of Radiation Safety
and Safeguards

Enclosure: Appendix A, Notice of Violation

cc w/encl:
Public Document Room (PDR)
Nuclear Safety Information Center (NSIC)
Commonwealth of Massachusetts

bcc w/encl:
Region I Docket Room (w/concurrences)
Management Assistant, DRMA

RI:DRSS
Courtemanche/gcb

05/2/88


DRSS
Kinneman

05/2/88
OFFICIAL RECORD COPY

ML DL CLARK UNIV - 0001.1.0
05/02/88