Y ellow-

AUG 24 1988

Docket No. 50-425 License No. CPPR-109

Georgia Power Company ATTN: Mr W. G. Hairston, III Senior Vice President -Nuclear Operations P.O. Box 4545 Atlanta, GA 30302

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-425/88-26

This refers to the Nuclear Regulatory Commission (NRC) review conducted by M. Hunt during May 4 - 26, 1988. The review included an inspection of activities at your Vogtle facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed inspection report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

Your attention is invited of the unresolved item identified in the inspection report. This matter will be pursued during future inspections.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely.

Alan R. Herdt, Chief Engineering Branch Division of Reactor Safety

Enclosure: (See page 2)

8809070385 880824 PDR ADDCK 05000425 Q PNU

AUG 24 1988

Georgia Power Company

Enclosure:

2

NRC Inspection Report cc w/encls: R. P. McDonald, Executive Vice President, Nuclear Operations P. D. Rice, Vice President, Project Director C. W. Hayes, Vogtle Quality Assurance Manager G. B. Bockhold, Jr., General Manager Nuclear Operations L. T. Gucwa, Manager, Nuclear Safety and Licensing J. A. Bailey, Project Licensing Manager B. W. Churchill, Esq., Shaw, Pittman, Potts and Trowbridge D. Kirkland, III, Counsel, Office of the Consumer's Utility Council D. Feig, Georgians Against Nuclear Energy bcc w/encls:

E. Reis, OGC J. Hopkins, NRR M. Sinkule, RII DRS, Technical Assistant NRC Resident Inspector Document Control Desk State of Georgia

RII M/1044 MHunt 08/19/ 88



RII MSinkule

ENCLOSURE 1

List of Open Items

1. Unresolved Item 88-26-01

- a. The licensee does not have a ready means of demonstrating process conservatism in the current application of electrical-raceway safety-train separation criteria. The existing criteria vary in the prescriptive documents that reflect implementation of the Wyle Laboratories test data used as the bases for not installing fire separation barriers otherwise required by NRC Regulatory Guide 1.75.
- b. The licensee did not have or show the use of appropriate thermal separation criteria for minimum space between electrical raceways and thermally-hot equipment other than piping.
- c. The licensee readiness review did not carry out the planned review element of cable tray cover installation activities due to cable pulling operations then in progress.