fficise

AUG 2 8 1988

Docket Nos. 50-325, 50-324 License Nos. DPR-71, DPR-62

Carolina Power and Light Company ATTN: Mr. E. Utley Senior Executive Vice President Power Supply and Engineering and Construction P. O. Box 1551 Raleigh, NC 27602

Gentlemen:

SUBJECT: ENFORCEMENT CONFERENCE - BRUNSWICK UNITS 1 AND 2 DOCKET NOS. 50-325 and 50-324

This confirms the telephone conversation between J. L. Harness of your staff and P. E. Fredrickson of my staff on August 16, 1988, concerning an Enforcement Conference at the Region II Office, Atlanta, Georgia on September 8, 1988, at 9:00 a.m. We had requested this meeting to discuss: (1) recent, discovered instrument installation deficiencies and non-constructions in the instrument settings associated with High Pressure Coolant Injection (HPCI)/Reactor Core Isolation Cooling (RCIC) high steam line flow isolation; (2) apparent inadequate corrective action related to operability of safety-related DC motor operated valves; and (3) electrical switchboard operability as it relates to the apparent inadequacy of actions taken to identify and correct silicon bronze bolt failures. This meeting had been previously rescheduled from July 7, to July 20, 1988, on your request. However, as the scope broadened due to additional safety-related concerns a second rescheduling became necessary.

Should you have any questions regarding these arrangements, we will be pleased to discuss them.

Sincerely,

J. Nelson Grace Regional Administrator

cc: P. W. Howe, Vice President Brunswick Nuclear Project J. L. Harness, Plant General Manager

bcc: (See page 2)

8809080027 880826 PDR ADOCK 05000324 PNU Carolina Power and Light Company

2

.

bcc: NRC Resident Inspector DRS, Technical Assistant Document Control Desk State of North Carolina

