



Nebraska Public Power District

COOPER NUCLEAR STATION
P.O. BOX 98, BROWNVILLE, NEBRASKA 68321
TELEPHONE (402) 825-3811

CNSS887426

September 2, 1988

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Reference 1: ASME Section XI, 1980 Edition, Winter 1981 Addenda, Article
IWA-6000.

Subject: Section XI Code Reports
Cooper Nuclear Station
NRC Docket No. 50-298, DPR-46


Gentlemen:

Pursuant to the reporting requirements of Reference 1, the subject code reports are submitted as enclosures to this letter for review by your office.

Enclosure 1, "Owner's Report for Inservice Inspections", (Form NIS-1), documents Inservice Inspection activities conducted at Cooper Nuclear Station during refueling outage number eleven (Spring 1988 Refueling Outage). Enclosure 2, "Owner's Report for Repairs and Replacements", (Form NIS-2), documents Repair and Replacement activities conducted at Cooper Nuclear Station during operating cycle number eleven and refueling outage number eleven.

Please contact E. M. Mace, Engineering Manager at Cooper Nuclear Station, if you should require additional information regarding this matter.

Sincerely,


G. A. Trevors
Division Manager of
Nuclear Support

GAT:SSF:ss

Enclosures

8809080165 880902
PDR ADDCK 05000298
G PNU

A047
11

U.S. Nuclear Regulatory Commission
September 2, 1988
Page 2

cc: NRC Regional Office
Region IV - USNRC

NRC Resident Inspector
Cooper Nuclear Station