Carolina Power & Light Company Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461-0429 September 1, 1988 FILE: B09-13510C SERIAL: BSEP/88-0854 U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555 BRUNSWICK STEAM ELECTRIC PLANT UNITS 1 AND 2 DOCKET NOS. 50-325 AND 50-324 LICENSE NOS. DPR-71 AND DPR-62 FOLLOW-UP TO SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.7.2 AND PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (1-SR-88-001) Gentlemen: During Unit 1 power operation concurrent with the Unit 2 1988 refueling/maintenance outage, a limiting condition for operation (LCO) was established on April 5, 1988, for fire protection deluge valve 1-FP-DV-22 to the sprinkler system of the units' common Service Water Building. This was done to permit isolation of the valve for repair of a leak involving the valve clapper latch seat ring Due to a temporary unavailability of qualified replacement parts, the specified 14-day time frame of the LCO was exceeded on April 19, 1988. Replacement parts to repair the valve are on-site and presently awaiting an Engineering evaluation prior to acceptance. It is expected required repairs and return of the valve to service will be accomplished during the upcoming Unit 1 refueling/maintenance outage, scheduled to commence on November 12, 1988. Until completion of the required repairs and return of the valve to service, the subject LCO, with appropriate fire watches and backup fire suppression equipment, will remain in effect. Very truly yours, J. L. Harness, General Manager Brunswick Steam Electric Plant MJP/bvc Enclosure cc: Mr. B. C. Buckley Dr. J. N. Grace BSEP NRC Resident Office