



PECO NUCLEAR

A Unit of PECO Energy

Michael P. Gallagher, P.E.
Plant Manager
Limerick Generating Station

PECO Energy Company
Limerick Generating Station
PO Box 2300
Sanatoga, PA 19464-0920
610 718 2000

10CFR 50.73

September 28, 1998

Docket Nos. 50-352
50-353

License No. NPF-39
NPF-85

U.S. Nuclear Regulatory Commission
Attn.: Document Control Desk
Washington, DC 20555

SUBJECT: Licensee Event Report
Limerick Generating Station - Unit 1 & 2

This LER reports a condition prohibited by Technical Specifications (TS) due to a calibration error for the Units 1 and 2 core spray internal line break detection instrumentation such that the setpoints were outside the required TS limit and the required TS actions were not taken within the specified time interval.

Reference:	Docket Nos. 50-352, 50-353
Report Number:	1-98-015
Revision Number:	01
Event Date:	February 28, 1996 Unit 1 February 16, 1995 Unit 2
Discovery Date:	July 11, 1998
Report Date:	September 28, 1998
Facility:	Limerick Generating Station P.O. Box 2300, Sanatoga, PA 19464-2300

This LER is being submitted pursuant to the requirements of 10CFR50.73(a)(2)(i)(B). This revision makes editorial corrections to the description of the event for clarification and consistency. *Jerr*

Very truly yours,

020011

cc: H. J. Miller, Administrator Region I, USNRC
A. L. Burritt, USNRC Senior Resident Inspector, LGS

9810020234 980928
PDR ADOCK 05000352
S PDR