MAY 1 0 1988

Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President Nuclear Edison Plaza 300 Macison Avenue Toledo, OH 43652

Gentlemen:

This refers to the routine safety inspection conducted by Mr. J. H. Neisler of this office on April 11-29, 1988, of activities at Davis-Besse Nuclear Power Station authorized by NRC Operating License No. NPF-3 and to the discussion of our findings with Mr. L. Ramsett and other members of your staff at the conclusion of the inspection. The purpose of this inspectior was to examine the licensee's implementation of commitments to Generic Letter 83-28.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.


Sincerely,

Winging organis of to to harrison

J. J. Harrison, Chief Engineering Branch

Enclosure: Inspection Report No. 50-346/88011(DRS)

See Attached Distribution



8805130175 880510 PDR ADOCK 05000346

DCD

Gardner



MAY 1 0 1988

Toledo Edison Company

Distribution

. .

1

cc w/enclosure: L. Storz, Plant Manager DCD/DCB (RIDS) Licensing Fee Management Branch Resident Inspector, RIII Harold W. Kohn, Ohio EPA James W. Harris, State of Ohio Robert M. Quillin, Ohio Department of Health State of Ohio, Public Utilities Commission