Docket No. 50-456 Docket No. 50-457

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the routi \circ safety inspection conducted by Mr. F. Maura of this office on April 19-27, 1988, of the actions taken regarding previous inspection items at the Braidwood Station, Units 1 and 2 authorized by NRC Operating Licenses No. NPF-72 and NPF-75 and to the discussion of our findings with Mr. D. E. O'Brien at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In a letter dated March 23, 1988, from Mr. L. D. Butterfield to Mr. A. B. Davis, Commonwerlth Edison disagreed with two of the violations contained in our February 2, 1988, letter to you. These violations dealt with failure to record deficient conditions involving test BwPT RY-50, and failure to review procedures for adequacy involving test BwPT-RC-52. We have reviewed both violations, in paragraphs 2.k and 2.n respectively, in the attached report. Based on our review, we are withdrawing as an example of violation the failure to record a deficient condition during the performance of BwPT RY-50. However, the violation associated with test BwPT RC-52 is still applicable.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

1E01

We will gladly discuss any questions you have concerning this inspection.

Sincerely.

G. C. Wright, Chief Operations Branch

Enclosure: Inspection Reports No. 50-456/88014; and No. 50-457/88015

cc w/enclosure:
T. J. Maiman, Vice President,
PWR Operations
H. Bliss, Nuclear
Licensing Manager
M. Wallace, Manager of Projects
M. Lohmann, Project Construction
and Startup Superintendent
W. Vahle, Construction
Superintendent

Superintendent
R. E. Querio, Station Manager
P. L. Barnes, Regulatory
Assurance Supervisor
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Braidwood
Resident Inspector, RIII Byron
D. W. Cassel, Jr., Esq.
Richard Hubbard

J. W. McCaffrey, Chief, Public Utilities Division H. S. Taylor, Quality Assurance Division

Division
E. Chan, OGC
G. Berry, OGC
Stephen P. Sands, NRR
The Honorable A. Dixon Callihan, ASLB
The Honorable Richard F. Cole, ASLB
The Honorable Ivan W. Smith, ASLB
The Honorable Gary J. Edles, ASLAP
The Honorable Dr. W. Reed Johnson, ASLAP
The Honorable Christine N. Kohl, ASLAP

RIII

maura/ky

style

Phyllips

RIII Hinds 05-06-88

RIII