

Illinois Power Company Clinton Power Station P.O. Bo., 678 Clinton, IL. 61727 Tel. 217 935-5623 Fax. 217 935-4632

Walter G. MacFarland IV Senior Vice President and Chief Nuclear Officer

> U-603083 2C.220

September 28, 1998

Docket No. 50-461

10CFR50.73

Document Control Desk Nuclear Regulatory Commission Washington, D.C. 20555

Subject:

Clinton Power Station - Unit 1

Licensee Event Report No. 1998-030-00

Dear Madam or Sir:

Enclosed is Licensee Event Report (LER) No. 1998-030-00: <u>Insufficient Suppression Pool Makeup Volume to Meet the Design Basis Suppression Pool Level Requirements Following a Loss of Coolant Accident</u>. This report is being submitted in accordance with the requirements of 10CFR50.73.

The enclosed report contains the following commitments:

 This event is under investigation. A revision will be issued to this report identifying the cause, corrective actions, safety significance, and previous similar event information.

Sincerely yours,

Walter G. MacFarland, IV Senior Vice President and Chief Nuclear Officer

JRF/krk

Enclosure

cc: NRC Clinton Licensing Project Manager

NRC Resident Office, V-690

Acting Regional Administrator, Region III, USNRC

Illinois Department of Nuclear Safety

INPO Records Center

9810020349 980928 PDR ADOCK 05000461 S PDR