



Commonwealth Edison Co.

Braidwood Station
RR 1, Box 81
Braceville, IL 60407
Telephone 815/458-2801

February 24, 1986

Mr. James G. Keppler
Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

SUBJECT: Braidwood Station Units 1 and 2
Supplemental Response to Inspection Report
Nos. 50-456/85-008 and 50-457/85-008
NRC Docket Nos. 50-456/50-457

REFERENCE: (a) J.J. Harrison letter to C. Reed
dated April 18, 1985

(b) D.L. Farrar letter to J.G. Keppler
dated May 15, 1985

Dear Mr. Keppler:

This letter supplements our Reference (b) response to part b of the violation identified in the Reference (a) Inspection Report (Item 456/85-008-10b). In assessing the adequacy of the implementation of corrective actions identified in response to this item, it was determined that additional action should be taken. The enclosure to this letter documents that action.

Should you or your staff have any further questions on this matter, please direct them to this office.

Very truly yours,

8603040212 860224
PDR ADOCK 05000456
G PDR

L.O. DelGeorge
Assistant Vice President

LOD/pav

Enclosure

cc: NRC Resident Inspector - Braidwood

12511

FEB 26 1986

11
-101

ENCLOSURE

Supplemental Response to
Inspection Report 456/85-008 and 457/85-008
Item 456/85-008-10b

The Braidwood Project Construction Department (PCD) has assessed the adequacy of using tape as a protective covering method. PCD has directed Phillips, Getschow Company (PGCo) to utilize tape only as a protective covering for temporary storage of pipe and valves. PGCo was directed to utilize metal, plastic, wood or other durable material which is adequately secured with tape or other qualified adhesive as protective covering for pipe, valves, etc. in non-temporary storage. PGCo will initiate any necessary procedure changes as well as any remedial field work to upgrade protective covers for pipe, valves, etc.

Implementation of these measures is expected by March 7, 1986.