



Entergy Operations, inc.
P.O. Box 8
Kilona, LA 70066
Tel 504 739 6242

Early C. Ewing, III
Director
Nuclear Safety & Regulatory Affairs
Waterford 3

W3F1-98-0162
A4.05
PR

October 1, 1998

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555

Subject: Waterford 3 SES
Docket No. 50-382
License No. NPF-38
Reporting of Licensee Event Report

Gentlemen:

Attached is Licensee Event Report (LER) 98-018-00 for Waterford Steam Electric Station Unit 3. This report provides details of a situation in which Technical Specification 3.0.3 was entered due to both trains of Shield Building Ventilation being inoperable simultaneously. This condition is being reported pursuant to 10CFR50.73(a)(2)(i)(B).

Very truly yours,

E.C. Ewing
Director,
Nuclear Safety & Regulatory Affairs

ECE/ALL/rtk
Attachment

cc: E.W. Merschoff (NRC Region IV), C.P. Patel (NRC-NRR),
A.L. Garibaldi, J.T. Wheelock - INPO Records Center,
J. Smith, N.S. Reynolds, NRC Resident Inspectors Office,
Administrator - LRPD

050023

9810050138 981001
PDR ADOCK 05000382
S PDR