



Log # TXX 88650
File # 10110
909.2
Ref. # 10CFR50.55(e)

September 2, 1988

William G. Council
Executive Vice President

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
SERVICE WATER SYSTEM WATER HAMMER
SDAR: CP-87-130 (SUPPLEMENTAL REPORT)

Gentlemen:

On January 6, 1988, we notified you via our report logged TXX-88034 of a reportable deficiency involving Service Water System water hammer and column separation at the inlet and outlet of the emergency diesel generator jacket water coolers which can occur subsequent to a service water pump trip. Our last report was logged TXX-88459, dated May 13, 1988. The purpose of this supplemental report is to update the corrective action implementation schedule for this issue.

The estimated completion date for installation of vacuum breakers in the Unit 1 emergency diesel generator jacket water coolers has been revised to December 13, 1988. The completion schedule for Unit 2 has not changed.

Very truly yours,

W. G. Council

MCP/grr

c-Mr. R. D. Martin, Region IV
Resident Inspectors CPSES (3)

8809130330 880902
PDR ADOCK 05000445
S PDC

JEZ7
1/0