Mr. James Knubel Chief Nuclear Officer

Power Authority of the State of

New York 123 Main Street White Plains, NY 10601

SUBJECT: JAMES A. FITZPATRICK NUCLEAR POWER PLANT - DRAFT REQUEST FOR

ADDITIONAL INFORMATION REGARDING GENERIC LETTER 96-06

(TAC NO. M96812)

Dear Mr. Knubel:

On July 30, 1998, you provided additional information regarding your response to Generic Letter 96-06, "Assurance of Equipment Operability and Containment Integrity During Design Basis Accident Conditions." The NRC staff has determined that additional information regarding your response will be required to complete its review of this issue. A draft copy of the information request is provided in the enclosure. Please review this request and provide your comments and proposed schedule for your response. You may provide this information to me by telephone at (301) 415-1470.

Sincerely.

Original Signed by:

Joseph F. Williams, Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-333

Enclosure: As stated

cc w/encl: See next page

DISTRIBUTION:

Docket File

S. Little

**PUBLIC** PDI-1 R/F J. Williams

J. Zwolinski

OGC

ACRS

S. Baiwa

JWilliams/rst

NAME

DATE

C. Hehl, Region I

DOCUMENT NAME: G:\FITZ\M96812A.RAI

NAC FALE CENTER COPY

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy T2C for 9/22/98 OFFICE D:PCI-1 PM:PDI-1 LA:PDI-1

SLittle Me Grango SBajwa HOO 09/ 198 for 9/28/98 09/79/98 09/29/98 Official Record Copy Mr. James Knubel
Chief Nuclear Officer
Power Authority of the State of
New York
123 Main Street
White Plains, NY 10601

SUBJECT: JAMES A. FITZPATRICK NUCLEAR POWER PLANT - DRAFT REQUEST FOR ADDITIONAL INFORMATION REGARDING GENERIC LETTER 96-06 (TAC NO. M96812)

Dear Mr. Knubel:

On July 30, 1998, you provided additional information regarding your response to Generic Letter 96-06, "Assurance of Equipment Operability and Containment Integrity During Design Basis Accident Conditions." The NRC staff has determined that additional information regarding your response will be required to complete its review of this issue. A draft copy of the information request is provided in the enclosure. Please review this request and provide your comments and proposed schedule for your response. You may provide this information to me by telephone at (301) 415-1470.

Sincerely,

Original Signed by:

Joseph F. Williams, Project Manager Project Directorate I-1 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-333

Enclosure: As stated

cc w/encl: See next page

DISTRIBUTION:

Docket File

S. Little

PUBLIC

J. Williams

PDI-1 R/F

OGC

J. Zwolinski

ACRS

S. Bajwa

C. Hehl, Region I

DOCUMENT NAME: G:\FITZ\M96812A.RAI

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy TLC for 9/02/98

OFFICE	PM:PDI-1	LA:PDI-1	D:PCI-1	
Annexemples of the second	JWilliams/rsl/	SLittle ME GUANA		
DATE	09/29/98 /	09/ 198 fox 9/28/98	09/19/98	

Official Record Copy

James Knubel
Power Authority of the State
of New York

CC:

Mr. Gerald C. Goldstein Assistant General Counsel Power Authority of the State of New York 1633 Broadway New York, NY 10019

Resident Inspector's Office U. S. Nuclear Regulatory Commission P.O. Box 136 Lycoming, NY 13093

Mr. Harry P. Salmon, Jr.
Vice President - Engineering
Power Authority of the State
of New York
123 Main Street
White Plains, NY 10601

Ms. Charlene D. Faison
Director Nuclear Licensing
Power Authority of the State
of New York
123 Main Street
White Plains, NY 10601

Supervisor Town of Scriba Route 8, Box 382 Oswego, NY 13126

Mr. Eugene W. Zeltmann
President and Chief Operating
Officer
Power Authority of the State
of New York
99 Washington Ave., Suite No. 2005
Albany, NY 12210-2820

Charles Donaldson, Esquire Assistant Attorney Genera! New York Department of Law 120 Broadway New York, NY 10271 James A. FitzPatrick Nuclear Power Plant

Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, PA 19406

Mr. F. William Valentino, President New York State Energy, Research, and Development Authority Corporate Plaza West 286 Washington Avenue Extension Albany, NY 12203-6399

Mr. Richard L. Patch, Director Quality Assurance Power Authority of the State of New York 123 Main Street White Plains, NY 10601

Mr. Gerard Goering 28112 Bayview Drive Red Wing, MN 55066

Mr. James Gagliardo Safety Review Committee 708 Castlewood Avenue Arlington, TX 76012

Mr. Arthur Zaremba, Licensing Manager James A. FitzPatrick Nuclear Power Plant P.O. Box 41 Lycoming, NY 13093

Mr. Paul Eddy
New York State Dept. of
Public Service
3 Empire State Plaza, 10th Floor
Albany, NY 12223

Michael J. Colomb Site Executive Officer James A. FitzPatrick Nuclear Power Plant P.O. Box 41 Lycoming, NY 13093



## UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

September 29, 1998

Mr. James Knubel Chief Nuclear Officer Power Authority of the State of New York 123 Main Street White Plains, NY 10601

SUBJECT: JAMES A. FITZPATRICK NUCLEAR POWER PLANT - DRAFT REQUEST FOR

ADDITIONAL INFORMATION REGARDING GENERIC LETTER 96-06

(TAC NO. M96812)

Dear Mr. Knubel:

On July 30, 1998, you provided additional information regarding your response to Generic Letter 96-06, "Assurance of Equipment Operability and Containment Integrity During Design Basis Accident Conditions." The NRC staff has determined that additional information regarding your response will be required to complete its review of this issue. A draft copy of the information request is provided in the enclosure. Please review this request and provide your comments and proposed schedule for your response. You may provide this information to me by telephone at (301) 415-1470.

Sincerely

Joseph F. Williams, Project Manager

Project Directorate I-1

Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-333

Enclosure: As stated

cc w/encl: See next page

## JAMES A. FITZPATRICK NUCLEAR POWER PLANT

## GENERIC LETTER 96-06 - ASSURANCE OF EQUIPMENT OPERABILITY AND CONTAINMENT INTEGRITY DURING DESIGN BASIS ACCIDENT CONDITIONS

## DRAFT REQUEST FOR ADDITIONAL INFORMATION

1. In its July 30, 1998, submittal, the New York Power Authority (NYPA, also known as the Power Authority of the State of New York) indicated that a total of 23 pipe segment penetrations were potentially susceptible to thermally-induced pressurization. NYPA stated that 9 of these segments are Reactor Building Closed Loop Cooling (RBCLC) containment penetrations for which there would be no thermal pressurization damage due to the following two considerations. The first consideration is that fluid pressure would lift the air operated globe valves by pressurizing under the valve seats. The second consideration is that the isolation valves require manual isolation which does not occur until after 10 minutes following a loss-of-coolant accident which would preclude enough heatup within the penetrations to cause thermal pressurization.

Please provide the following information for these penetrations:

- A. Describe the applicable design criteria for the pip and valves. Include the required load combinations;
- Provide a drawing of the valve. Describe the method used to estimate the pressure at which the valve was determined to lift off its seat or leak. Discuss any sources of uncertainty associated with the estimated valve disk lift off or leakage pressure;
- C. Provide the maximum-calculated stress in the piping run based on the estimated lift off or leakage pressure;
- D. The licensee states that plant operating procedures only dire the operators to isolate the valves for these penetrations if there are symptoms of a breach in the RBCLC piping and that 10 minutes elapsed time is assumed for operator action. Describe how the plant operating procedures assure that the operators would not take action at any time prior to 10 minutes;
- E. Provide the maximum-calculated temperature and pressure for the pipe runs. Describe, in detail, the method used to calculate these pressure and temperature values. This description should include a discussion of the heat transfer model used in the analysis and the basis for the heat transfer coefficients used in the analysis. Include the lengths and thicknesses of the piping segments and the type and thickness of the insulation.
- 2. In its July 30, 1998, submittal, NYPA stated that 11 of the 23 pipe segment penetrations were evaluated for the thermal pressure conditions which would occur with the consideration that an isolation valve would lift off its seat to limit the pressure. For these, the licensee evaluated the pipe stresses due to thermal pressurization and other loads in accordance with ASME Appendix F criteria.

Please provide the following information for these penetrations:

- A. The acceptance criteria includes a load combination for a Normal/Upset Primary Stress condition which is 2.4 times the basic allowable stress at temperature. Since Appendix F does not address Normal/Upset conditions, the staff believes that the 2.4 factor is inappropriate for these conditions. Please provide clarification regarding the appropriate criteria for Normal/Upset thermal pressurization conditions and how it is applied to the components evaluated;
- B. The licensee does not combine thermal pressurization loads with occasional hydrodynamic loads. The licensee states that hydrodynamic loads will dissipate before internal pressure can significantly increase. Describe in detail the hydrodynamic loads which can occur for these penetrations and when they specifically occur relative to thermal pressurization for licensing basis events;
- Describe the applicable design criteria for the isolation valves. Include the required load combinations;
- D. Provide a drawing of the valves. Describe the method used to estimate the pressure at which the valve was determined to lift off its seat or leak. Discuss any sources of uncertainty associated with the estimated valve disk lift off or leakage pressure;
- E. In addition, for two of these 11 penetrations (X-18 and X-19), NYPA states that the leak path generated through one of the isolation valves is "non-resealing" due to the seat materials. This infers that the leak would be caused due to significant deformation of the valve internals. This scenario appears to involve much more uncertainty in determining the peak pressure than for a valve where fluid pressure under a disk acts against a linear-elastic spring resistance. The licensee also relies on the other isolation valve remaining leak-tight until this valve leaks to relieve the fluid pressure. Address the uncertainty in determining the peak pressure and how it is assured that the sole remaining containment isolation valve will remain leak-tight and not undergo similar damage during the pressurization.
- 3. In its submittal dated July 30, 1998, NYPA stated that Pipe Line Numbers 3"-WL-151-1A and 1B may also be subject to thermal pressurization, but were not analyzed since they are not required for containment integrity. Please verify that containment isolation is the only safety function of this system.
- 4. In its submittal dated July 30, 1998, the licensee also stated that for High Pressure Coolant Injection penetration X-226, isolation valve leakage tests would be required, "perhaps on a periodic basis," to verify sufficient leakage to prevent pressure locking of the valves. Please clarify the specific frequency of the tests necessary to verify the required leakage.